
### HOPE'S Standard



# GALVANIZED SASHES

LIST No. 226

### S SASHE GALVANIZE S OPE




INSIDE ELEVATIONS


### HOPE'S Standard SASHES

VENTILATORS are made separately of universal casement sections with welded corners, without loose or applied linings, afterwards bedded and screwed into the sash frames.


COUPLING. Large windows can be made of standard units coupled together with suitable mullions and transomes. Units and coupling members are despatched separately ready for assembly on job by the fixing contractor.




### COUPLING MEMBER



FULL SIZE DETAILS




# 田 SASH GALVANIZE OPE



INSIDE ELEVATIONS

### SPECIFICATION





POSITIONS OF FIXING HOLES IN RED


### SPECIFICATION


HOPE'S STANDARD SASHES are prepared for inside putty glazing with a flanged frame bar all round, suitable for fixing to brickwork, concrete or steelwork. Lugs or bolts and nuts for fixing are sent separately. VENTILATORS, unless specified otherwise, are HORIZONTALLY CENTRE-HUNG, but may be hung at top or bottom without extra cost when specially ordered. HORIZONTALLY CENTRE-HUNG VENTI-LATORS are hung on bronze cup pivots and fitted with a bronze spring catch for hand, cord or pole operation. 10 18" TOP-HUNG VENTILATORS are hung on corner hinges and fitted with a bronze cam opener for hand or pole operation. 10 18 BOTTOM-HUNG VENTILATORS are hung on corner hinges and fitted with folding side arms, and bronze spring catch for hand, cord or pole operation. 3',03" HOPPER VENTILATORS with sheet steel side cheeks (despatched separately) can be supplied at 10 18" extra cost; fitted with brass spring catch for hand, SSF 53 SS 53 cord or pole operation. SIZES are overall steel frames. 10 18 GLAZING. Holes are drilled and spring wire glazing clips are supplied. Special Metal Sash 3'03" Putty should be used. GLASS SIZES on back cover. FINISH. Hot-dip galvanized and delivered un-1'63" painted. 10 18 Handling, fixing and glazing instructions are sent with each consignment. SSF 54 SS 54 -3' 27"-SSF 56 SS 56 SSA 36 SSA 46 SSA 56 7.42 7 4. 1.08 7 th. 1,0<sup>8</sup>° 1.0g 4

POSITIONS OF FIXING HOLES IN RED










SASHES with FIRE ESCAPE CASEMENTS (shown below). Lower casements are side hung opening outwards, hinged on right-hand side looking from inside, and fitted with a bronze handle and peg stay. Upper ventilators are horizontally centre hung, unless ordered as top or bottom hung.



Fixing hole positions are shown in red.

Lugs are slotted and reversible and can be adjusted to suit brick courses.

When fixing is to steelwork or when composite windows of varying units are required, you are requested to apply to us for drawings showing overall sizes and construction.


### GEARING

We are designers and manufacturers of all types of Gearing, from hand-operated single units to electrically operated installations for long ranges of sashes.

For further details please ask for our List No. 180.

ALL PREVIOUS LISTS CANCELLED

# S 田 SASH GALVANIZE ${ m H}$ O ${ m E}$ '




INSIDE ELEVATIONS


### HOPE'S Standard SASHES

VENTILATORS are made separately of universal casement sections with welded corners, without loose or applied linings, afterwards bedded and screwed into the sash frames.


COUPLING. Large windows can be made of standard units coupled together with suitable mullions and transomes. Units and coupling members are despatched separately ready for assembly on job by the fixing contractor.



### COUPLING MEMBER



FULL SIZE DETAILS



## HOPE'S Standard HOT-DIP GALVANIZED STEEL SASHES

### GLASS SIZES

CLEARANCE HAS BEEN DEDUCTED

ALL FIXED LIGHT PANES ARE 1'-6" × 1'-0"

**VENTILATORS:** 







Horizontal Centre Hung,
Top Hung, Bottom Hung or Hoppers



Horizontal Centre Hung, Top Hung, Bottom Hung, Side Hung or Hoppers  $A = 1' - 3\frac{3}{8}'' \times 10\frac{5}{8}''$ 

 $B = 1' - 3\frac{3}{8}'' \times 1' - 0''$ 

 $C = 1' - 4\frac{5}{8}'' \times 10\frac{5}{8}''$ 

 $D = 1' - 4\frac{5}{8}'' \times 1' - 0''$ 

### HENRY HOPE & SONS LTD

Head Office and Works: Smethwick, Birmingham 40

Telephone: SMEthwick 0891

LONDON

17 Berners Street, W.1
Telephone: MUSeum 8412

MANCHESTER

Westminster Bank Chambers 3 York Street, Manchester 2 Telephone: DEAnsgate 3991-2 GLASGOW

I Blythswood Square, Glasgow C2

Telephone: DOUglas 4170

LEEDS

Provincial House Albion Street, Leeds Telephone: Leeds 20708-9